VELL DRILLER'S REPORT

State of Utah Division of Water Rights



Well Log

For additional space, use "Additional Well Data Form" and attach

Well Ide	ntificatio	n												
WATER RIGHT APPLICATION: 55-8973 (A69087)														
Owner	Owner Note any changes													
		Clark, Tho									AN 302 23 1993			
			1331 North Lakeview Drive Provo, UT 84604											
		FI	OV	Ο,	.01	_ () T (on/Engineer:_				
Well Loc	ation 1	lote ar	ıy ch	ange.	s									
		CC	UN	TY	. V	Va s	at	cch	1					
	NORTH 620 feet EAST 780 feet from the W4 Corner of SECTION 28, TOWNSHIP 5S, RANGE 5E, SLB&M.													
Location l	Location Description: (address, proximity to buildings, landmarks, ground elevation, local well #)													
Drillers Activity Start Date: 6/34/99 Completion Date: 7-15-59														
Check all that apply:														
New Repair Deepen Abandon Replace Public Nature of Use: IRR, STK, DOM														
DEPTH FROM	DEPTH (feet) FROM TO			BOREHOLE DIAMETER (in)					DRILLING	METHOD	DRILLING FLUID			
	45		83/4				ROTARY					WATER, BENTONITE		
45	305		77/8				, ,					11		
Well Log W P UNCONSOLIDATED CONSOLIDATED														
DEPTH FROM	A T E R	A R C S S G T M L I A R E E A L N A				B U H B L E L D R ROCK TYPE COLOR			COLOR	(incl	DESCRIPTIONS AND REMARKS (include comments on water quality if known.)			
0	8		×							BROWN	SURFACE			
8	43	x	X			<u>x</u> :	x >	<			SURFACE WATER			
43	131	,	、						BrdRock	Hellow	FRACHARD LAYERS.			
131	134	×	×		x						•			
134	305		- -						Bookerok	Wellow	Feachmed			
								***		Vertex				
	<u> </u>		1	\forall				+						
			1	$\dagger \dagger$		+	_	 						
			\dagger			+								
			+			-	-	-						
Static Water Level Date 7/15/99 Water Level 52 feet Flowing? Yes X No														
Date 7/15/99 Water Level 52 feet Flowing? Yes X No Method of Water Level Measurement STRIC Live If Flowing, Capped Pressure N/A PSI														
Point to Which Water Level Measurement was Referenced Stound														
									ground surface		et Temper	ature 46 🗆 °C 🕱 °F		